


421
202

3700
7-4

SEARCH
CONTAINER

10

FIG.1




YES

EVIDENCE
OF LEAKS
?

NO

SAMPLE SIDE
PORT AT DOME

16




YES

NO

REMOVE PROTECTIVE
FACEMASK FOR
SNIFF TEST

20



YES

NO

24
OPEN DOME COVER;
INSPECT DOME AREA

26
PROCEED TO HEATED
N₂ CLEANING

14
ASSESS LEAK;
SUBMIT
CONTAINER
FOR REPAIRS

00240 " 3003360





FIG.3



002707 5008960

FIG. 4A




FIG. 4B

